ASRockind Technical Reference - Q&A

Question	Intel Coffee Lake Platform doesn't work normally in sleep mode or hibernate mode on Windows 10 64-bit RS5, How do I fix it?
Release date	2020/4/16
Product	Coffee Lake Platform: IMB-1210-L, IMB-1210-D, IMB-1211-L, IMB-1211-D, IMB-1212, IMB-1213, IMB-1214, IMB-1215, IMB-1310, IMB-1311-L, IMB-1311-D, IMB-1312, IMB-1710
FAQ type	☐ Specification ■ OS & Driver ☐ Application ☐ BIOS/FW ☐ Others

Answer:

Intel has released the new VGA driver (ver: 25.20.100.6617) for Windows 10 64-bit RS5, and ASRock Industrial upload it to our official website. Please download the VGA driver and then install it to verify the function.

Link: http://asrock.pc.cdn.bitgravity.com/Drivers/Intel/VGA/VGA(v25.20.100.6617).zip