

## ASRockind Technical Reference - Q&A

<b>Question</b>	How do I cut off the power of USB port after I shut down my system?
<b>Release date</b>	2020/5/1
<b>Product</b>	All model
<b>FAQ type</b>	<input type="checkbox"/> Specification <input type="checkbox"/> OS & Driver <input checked="" type="checkbox"/> Application <input type="checkbox"/> BIOS/FW <input type="checkbox"/> Others

### **Answer:**

Please refer the following steps to disable USB standby power.

1. Boot up the system and press Del or F2 to enter BIOS.
2. Adjust Deep Sleep to [Enable]

(Path: BIOS> Advanced> Chipset configuration)

Note: To disable USB standby power, ACPI power on settings must be disabled.

(Path: BIOS> Advanced> ACPI Configuration)

